



3605^{Q&As}

Avaya Ethernet Routing Switch Implementation and Maintenance Exam

Pass Avaya 3605 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/3605.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

The exhibit indicates the two show commands from an edge Ethernet Routing Switch (ERS) 5520-24T- PWR an untagged frame arrives on port 10. which is configured as an access port To which VLAN will the packet be forwarded?

```
5520 Edge (SSH)
5520-24T-PWR#show vlan int info 10-11
      Filter      Filter
      Unregistered
Port  Frames      Frames      PVID PRI      Tagging      Name
-----
10   No           Yes           312  0      TagAll      Port 10
11   No           Yes           312  0      TagAll      Port 11
5520-24T-PWR#show vlan int vid 10-11
Port VLAN VLAN Name      VLAN VLAN Name      VLAN VLAN Name
-----
10   311  VLAN-311      312  VLAN-312
11   311  VLAN-311      312  VLAN-312
5520-24T-PWR#
```

- A. All untagged packets will be placed in the default VLAN (VLAN 1).
- B. All untagged packets will be discarded.
- C. All untagged packets will be placed in VLAN 311
- D. All untagged packets will be placed in VLAN 31?

Correct Answer: B

QUESTION 2

An existing enterprise network is using Ethernet Routing Switch (ERS) 8600 switches in the campus core. It has been determined that 10 Gigabit links are required to replace the existing 1 gigabit uplinks will affect is connections on each of the ERS 8600 switches. Which statement describes how to accomplish this requirement in each ERS 8600 chassis?

- A. Replace the two existing switches fabric modules with 8394SF systems.
- B. Replace the two existing switch fabric modules with 8692SF and Supermez2
- C. Replace the two existing 8616SXE modules with 8612XLRS modules.
- D. Replace the six 8683XLK modules with 8612XLRS.

Correct Answer: BC

QUESTION 3

A technician is configuring 802.1 Q tagging, VLACP with short timeout, untagged frames to be discarded. Which part of the network is being configured?



- A. layer 2 core
- B. layer 3 core
- C. the edge
- D. the uplinks

Correct Answer: D

QUESTION 4

While configuring packet capture Tool (PCAP), an Ethernet Routing Switch (ERS) 8600 switch has generated the following log:

pcapAllocateBuffer: malloc(96 Mbs) failed

Which event could have caused this log, and which course of action resolves the issue?

- A. The memory allocation failed to wrap. Set Pcmcia Wrap to true
- B. The packet capturing stopped. Enable the Buffer-wrap or reset the stats.
- C. The length of the IP frame is too long to capture. Turn on fragmentation
- D. There is not enough available memory for PCAP. Try with a lower value of buffer-size.

Correct Answer: D

QUESTION 5

A customer has security concerns with the current RADIUS authentication implementation and is asking to change all authentication requests from the ERS 8000 to be directed to their TACACS+ server.

What two differences exist between the authentication requests used by RADIUS and TACACS+ that would you cause this concern for the customer? (Choose two)

- A. TACACS+ is a TCP-based protocol.
- B. RADIUS does not support AES encryption.
- C. TACACS+ uses full packet encryption.
- D. RADIUS uses clear passwords.

Correct Answer: AC

[3605 VCE Dumps](#)

[3605 Practice Test](#)

[3605 Study Guide](#)