

HP0-S41^{Q&As}

Building HP Server Solution

Pass HP HP0-S41 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/hp0-s41.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.geekcert.com/hp0-s41.html

2024 Latest geekcert HP0-S41 PDF and VCE dumps Download

QUESTION 1

After installing DIMMs in all of the memory slots on a DL380p Gen8, only half of the memory can be seen. What is a probable cause of this issue?

- A. Hyper-threading is not enabled in the RBSU.
- B. Half of the DIMMs are a slower speed than the other half.
- C. Onlyone processor is installed.
- D. Half of the DIMMs are 135 volts, and the rest are 1.50 volts.

Correct Answer: B

QUESTION 2

Which tool can be used to run Insight Diagnostics offline?

- A. ROM Based Setup Utility (RBSU)
- B. Intelligent Provisioning
- C. Post Boot Menu (F12)
- D. Option ROM Configuration for Arrays (ORCA)

Correct Answer: B

QUESTION 3

Why would you update HP Intelligent Provisioning on Gen8/Gen9 ProLiant servers?

- A. To update the SA agent used by Insight Control server provisioning
- B. To get access to the latest diagnostic and configuration tools
- C. To improve the overall system performance
- D. To update micro-codes in RBSU/UEFI

Correct Answer: C

QUESTION 4

What is an advantage of HP APM for scale-out compute in the Apollo 8000?

A. More compute performance is realized.



https://www.geekcert.com/hp0-s41.html 2024 Latest geekcert HP0-S41 PDF and VCE dumps Download

- B. Fewer components and cables are required.
- C. Less potential capacity is needed.
- D. Measurement of interconnect throughput is more accurate.

Correct Answer: B

QUESTION 5

You are trying to log in to the Virtual Connect Manager of one of the c7000 enclosures, out the Virtual Connect Manager is disabled. What is a probable reason for this issue?

- A. The stacking link of the Onboard Administrator is disconnected
- B. The enclosure is managed by HR QneView
- C. The Virtual Connect Manager license is not enabled
- D. The Virtual Connect Manager and Onboard Administrator firmware versions are incompatible

Correct Answer: B

HP0-S41 Practice Test

HP0-S41 Study Guide

HP0-S41 Braindumps