



DES-4421^{Q&As}

Specialist - Implementation Engineer, PowerEdge MX Modular Exam

Pass EMC DES-4421 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/des-4421.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

Which feature requires an iDRAC Enterprise license for an MX sled?

- A. iDRAC Service Module
- B. Last Crash Screen
- C. Group Manager
- D. Storage Management

Correct Answer: C

Reference: https://i.dell.com/sites/csdocuments/Product_Docs/en/poweredge-mx740c-technical-guide.pdf?newtab=true (p.9)

QUESTION 2

What is a benefit of using scalable fabric architecture in the MX7000?

- A. Management of all servers and fabrics is done from the last chassis in the fabric
- B. Management of all fabrics is done from the third fabric in the chassis
- C. Management of all servers and fabrics is done from the lead chassis
- D. Management of all fabrics is done from the last chassis in the fabric

Correct Answer: C

Reference:

<https://infohub.delltechnologies.com/static/media/client/7phukh/d3df87a5-ddb7-4917-969d-24e249b52824.pdf>

QUESTION 3

Which protocol(s) does Redfish use?

- A. JSON and OData only
- B. JSON only
- C. JSON, OData, and SNMP
- D. OData only

Correct Answer: A

Reference: <https://www.dell.com/support/article/us/en/04/sln310624/redfish?lang=en>

**QUESTION 4**

A technician has replaced an MX chassis tub. They complete the tub installation and power on the chassis. They notice that the KVM is no longer functional. What should the technician do after confirming the KVM feature is still enabled in OME-M?

- A. Ensure all cables connecting the tub to the left ear control panel are connected properly
- B. Ensure all power supplies are connected and powered-on
- C. Ensure all cables connecting the tub to the right ear control panel are connected properly
- D. Ensure all installed Management Modules are connected to the network

Correct Answer: A

QUESTION 5

An administrator is connecting two MX840c to an MX5016s. The MX5016s is configured in Enclosure Assigned mode. What should the requirements of this mode be to avoid configuration issues?

- A. MX745P with a cluster aware OS
- B. MX745P with no OS restrictions
- C. HBA330MMZ with no OS restrictions
- D. HBA330MMZ with a cluster aware OS

Correct Answer: A

Reference: https://i.dell.com/sites/csdocuments/Product_Docs/en/poweredge-mx5016s-mx5000s-technical-guide.pdf (p.10)

[DES-4421 PDF Dumps](#)

[DES-4421 Practice Test](#)

[DES-4421 Study Guide](#)