



DES-6321^{Q&As}

Specialist - Implementation Engineer - VxRail Appliance Exam

Pass EMC DES-6321 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/des-6321.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

A system administrator attempts to use the VxRail REST API to obtain system health status for their VxRail environment. The system returns the following error code: 401. What should the administrator do to address this issue?

- A. Provide vCenter credentials with sufficient rights.
- B. Connect to vCenter GUI and try the command again
- C. Wait five minutes and try the command again
- D. Ensure that the VxRail Manager IP is correct

Correct Answer: A

QUESTION 2

You have determined that you need to execute a RASR factory upgrade of a VxRail v4.7.1xx node You download the RASR ISO from the Dell Support site. What is the correct order of steps to finish the upgrade?

Select and Place:

Map the RASR ISO as a Virtual CD/DVD	Step 1
Update firmware	Step 2
Access iDRAC and launch Virtual Console to the VxRail node	Step 3
Select "R" in the RASR menu	Step 4
Boot the node from the Virtual CD/DVD ISO	Step 5

Correct Answer:



<input type="text"/>	Access iDRAC and launch Virtual Console to the VxRail node1
<input type="text"/>	Map the RASR ISO as a Virtual CD/DVD
<input type="text"/>	Boot the node from the Virtual CD/DVD ISO
<input type="text"/>	Select "R" in the RASR menu
<input type="text"/>	Update firmware

QUESTION 3

An implementation engineer is attempting to add a new node to a 3 node VxRail cluster.

What is the minimum VxRail code version that no longer requires the fourth node to match the first three nodes?

- A. 4.0.302
- B. 4.0.502
- C. 4.5.070
- D. 4.5.150

Correct Answer: D

Reference: <https://www.vstecs-dellsolutions.com/wp-content/uploads/2018/10/vxrail-faq.pdf>

QUESTION 4

Which port configuration is invalid on the integrated NIC of a VxRail node?

- A. 2 x 25 GbE SFP28
- B. 2 x 10 GbE RJ45
- C. 2 x 10 GbE SFP+
- D. 2 x 1 GbE RJ45

Correct Answer: D

Reference: <https://www.dell EMC.com/en-us/collaterals/unauth/technical-guides-support-information/products/converged-infrastructure/h15300-vxrail-network-guide.pdf> (10)



QUESTION 5

A company has a simple, 4 node VxRail cluster. The VxRail is running version 3.5 and utilizes a vSphere standard license. The company has asked for a VxRail software upgrade.

What are the steps for the upgrade?

- A. Log in to VxRail Manager, select "Internet Upgrade", then follow the prompts.
- B. Log in to support.emc.com and download the upgrade packages. Next, open VxRail Manager, select "Off-line Upgrade", then follow the prompts.
- C. Place all four nodes into maintenance mode. Next, log in to VxRail Manager, select "Internet Upgrade", then follow the prompts.
- D. Contact Dell EMC support to request the upgrade to the VxRail cluster.

Correct Answer: B

[DES-6321 VCE Dumps](#)

[DES-6321 Study Guide](#)

[DES-6321 Exam Questions](#)