



DES-DD23^{Q&As}

Implementation Engineer - PowerProtect DD

Pass EMC DES-DD23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/des-dd23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

A PowerProtect DD appliance with two expansion shelves is being installed in a customer-provided rack.

When cabling the controller to the shelves, what is connected to the host port on the last shelf in the chain?

- A. Expansion port of the upstream shelf
- B. Host port of the controller
- C. Expansion port of the controller
- D. Host port of the downstream shelf

Correct Answer: A

QUESTION 2

An administrator has retained snapshots for a single MTree and is trying to create a new one. An error message is received. What is the reason for the failure?

- A. The maximum number of snapshots has been exceeded
- B. The user does not have the permission to retain more snapshots
- C. There are not enough snapshot licenses
- D. The DDOS needs to be upgraded

Correct Answer: A

QUESTION 3

A storage administrator finished the zoning between the PowerProtect DD and the NetWorker backup server. How can they verify that the zoning was completed properly and the server HBA are visible?

- A. scsitarget initiator show list
- B. scsitarget show initiator list
- C. scsitarget show initiator
- D. scsitarget initiator list

Correct Answer: A

Reference: <https://www.delltechnologies.com/asset/en-us/products/data-protection/technical-support/docu96469.pdf>
(30)



QUESTION 4

An administrator is migrating their old cloud tier-enabled Data Domain to a new PowerProtect DD appliance with cloud tier. During migration, the administrator recognizes that file system cleaning on the source system is not possible. What is the most likely cause of this behavior?

- A. Migration will restrict all activities on source systems.
- B. Migration will restrict all activities on both systems.
- C. Filesystem is disabled on source system.
- D. Source system is running in restricted mode.

Correct Answer: A

QUESTION 5

A PowerProtect DD system is configured for VTL. The backup application requires a minimum tape capacity of 800 GB. What is the minimum tape type to support this requirement?

- A. LTO-5
- B. LTO-3
- C. LTO-2
- D. LTO-4

Correct Answer: D

Reference: <https://www.delltechnologies.com/asset/en-us/products/data-protection/technical-support/docu95865.pdf> (359)

[DES-DD23 VCE Dumps](#)

[DES-DD23 Study Guide](#)

[DES-DD23 Exam Questions](#)