



E22-285^{Q&As}

VxRail Appliance 4.x Deployment and Implementation Exam

Pass EMC E22-285 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/e22-285.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

During the deployment of VxRail, you import a JSON file and attempt a validation. An error indicates that node 1 cannot access the other nodes. When you look at the Nexus switchport configuration, you see the following on all VxRail ports: interface TenGigabitEthernet 1/x switchport switchport trunk switchport trunk allow vlan all What is a possible reason for this situation?

- A. "switchport trunk native vlan x" is not configured
- B. "switchport access vlan x" is not configured
- C. "switchport trunk vlan x" is not configured
- D. "switchport vlan x" is not configured

Correct Answer: B

QUESTION 2

What is a requirement for Top of Rack (ToR) switch VxRail node ports?

- A. Enable Spanning Tree
- B. Disable IGMP Snooping
- C. Enable IGMP Querier
- D. Disable Link Aggregation

Correct Answer: D

QUESTION 3

What is the VxRail maximum cluster size if using only 1 GbE links?

- A. 8
- B. 16
- C. 32
- D. 64 with an RPQ

Correct Answer: A

QUESTION 4

A company has a simple, 4 node VxRail cluster. The VxRail is running version 3.5 and utilizes a vSphere



standard license. The company has asked for a VxRail software upgrade.

What are the steps for the upgrade?

- A. Log in to VxRail Manager, select "Internet Upgrade", then follow the prompts.
- B. Log in to support.emc.com and download the upgrade packages. Next, open VxRail Manager, select "Off-line Upgrade", then follow the prompts.
- C. Place all four nodes into maintenance mode. Next, log in to VxRail Manager, select "Internet Upgrade", then follow the prompts.
- D. Contact Dell EMC support to request the upgrade to the VxRail cluster.

Correct Answer: B

QUESTION 5

A BMC interface webpage is reachable but unresponsive. What should be done to resolve this problem?

- A. NDU to latest bundle of VxRail software
- B. Reboot the node
- C. Reset the BMC through `/tmp/vspexblue/bin/ipmitool mc reset cold`
- D. Upgrade the BMC firmware

Correct Answer: B

[E22-285 PDF Dumps](#)

[E22-285 Study Guide](#)

[E22-285 Braindumps](#)