



HPE2-T35^{Q&As}

Using HPE OneView

Pass HP HPE2-T35 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/hpe2-t35.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

Your customer added some Gen10 servers to an environment managed by HPE OneView. The position of the Gen10 servers in the intelligent racks is not automatically detected. What can cause this problem?

- A. Gen10 servers are mixed with Gen9 or Gen8 servers, which is not supported.
- B. Intelligent Rack is not properly licensed in HPE OneView.
- C. Location sensor is not enabled for Gen10 servers.
- D. Gen10 servers do not support Location Discovery Services.

Correct Answer: D

QUESTION 2

How does HPE OneView simplify infrastructure management? (Choose two.)

- A. Manages physical servers and virtual machines.
- B. Provides unified platform that supports management across compute, storage, and fabric.
- C. Provides integrations with 3rd Party infrastructure automation tools through an API driven interface.
- D. Provides industry leading infrastructure security through Silicon Root of Trust.

Correct Answer: BC

QUESTION 3

An administrator needs to customize the BIOS and local RAID configuration for a collection of HPE ProLiant servers. What should the administrator use to accomplish this task?

- A. Smart Start Scripting Toolkit
- B. Global Dashboard
- C. server hardware
- D. Server Profile Template

Correct Answer: B

QUESTION 4

- A. Settings
- B. Server Hardware



C. Data Centers

D. Power Delivery Devices

Correct Answer: B

QUESTION 5

After HPE BL460c Gen10 server failure, the system operator quickly replaces the failed server with a new one in the same bay. However, the server profile does not get applied automatically. What may have prevented the profile from being applied?

A. The affinity value is set to "device bay + server hardware".

B. The server profile attribute is set to "Occupied".

C. The firmware "Force installation" option is selected.

D. The Volume Template properties are locked.

Correct Answer: A

[Latest HPE2-T35 Dumps](#)

[HPE2-T35 Exam Questions](#)

[HPE2-T35 Braindumps](#)