7003.1 Q&As

Avaya Communication Server 1000 for Avaya Aura Implementation Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.geekcert.com/7003-1.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

Instant Download After Purchase
100% Money Back Guarantee
365 Days Free Update
800,000+ Satisfied Customers

QUESTION 1

Upon accessing Subscriber Manager, you discover that the Subscriber Manager database does not accurately reflect all the telephones managed under the Subscriber Manager database.

Which Subscriber Manager operation is required to update the Subscriber Manager database with the communication Server 1000 telephones?

A. Account Synchronization

B. LDAP Synchronization

C. Publish Accounts

D. CSV Subscriber Synchronization

Correct Answer: A

QUESTION 2

A customer has a Communication Server (CS) 1000 Rls. 7x Co-Resident system with a Media Gateway Controller and Media Cards and has completed the configuration of all elements and they are all active and known to the Call Server. The customer wants to add all the elements to the Security Domain.

Which Overlay 117 commands used to add the element to the Security Domain?

A. JoinSecDomain

B. Join ucmSecurity element

C. Register ucmsecurity device

D. Register ucmSecurity system

Correct Answer: D

QUESTION 3

A technician has configured a new media gateway by connecting to the serial port for the MGC and entering network information for the card as well as the IP address for the Primary call server. When the MGC reboots, the faceplates displays UNRG. The Call Server console `IPMG registration denied\\'.

What should be done to solve this problem?

A. Ping from the MGC to the call server over the E-LAN

B. Check to ensure the TLAN cable for the MGC is connected and active

C. Check to ensure the IPMG has been configured on the call server

D. Power cycle the MGC card to force it to register

Correct Answer: C

QUESTION 4

A customer has completed installing and configuring a new CPMG Co-Resident Platform. The Gateway controller has rebooted and the customer has verified the LED display shows the loop and shelf of the media gateway. The customer is satisfied the gateway controller has successfully registered to the Call Server. The customer logs into the system Manager and accesses the UCM Element list and the Gateway controller does not appear in the Element List with the other registered elements in the security domain.

What is the recommended course of action for the customer to ensure the Gateway Controller appears in the Element List?

A. Log into the Gateway controller card using CLI and enter statSecDomain.

B. Log into the Gateway controller card using CLI and enter joinSecDomain.

C. Log into the Gateway controller card using CLI and enter registerSecDomain.

D. Log into the system and access Overlay 117 and enter register ucmsecure device.

Correct Answer: B

QUESTION 5

A customer that has an existing option 11C chassis system with an SCC card is planning t o upgrade to a Communication Server (Rls.) 1000E Rls. 7x system. A CPMG Co-Resident server card will be installed.

Which action must be completed manually?

A. The digital Trunk Numbers must be reprogrammed with a new format

B. The IP Phones Terminal Numbers must be entered with a new format

C. The IP address for each Ip media Gateway must be entered in LD 97

D. The tone Receiver Terminal Numbers must be re-Programmed with new format

Correct Answer: C

Latest 7003.1 Dumps 7003.1 Study Guide 7003.1 Braindumps