# 300-430<sup>Q&As</sup>

300-430<sup>Q&As</sup>

Implementing Cisco Enterprise Wireless Networks (ENWLSI)

## Pass Cisco 300-430 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

**https://www.geekcert.com/300-430.html**

### 100% Passing Guarantee
### 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

**Instant Download** After Purchase

**100% Money Back** Guarantee

**365 Days** Free Update

**800,000+** Satisfied Customers

**QUESTION 1**

Where is a Cisco OEAP enabled on a Cisco Catalyst 9800 Series Wireless Controller?

A. RF Profile

B. Flex Profile

C. Policy Profile

D. AP Join Profile

Correct Answer: B

https://www.cisco.com/c/en/us/td/docs/wireless/controller/9800/configguide/b_wl_16_10_cg/flex connect.html

**QUESTION 2**

Which role does an engineer configure for administrative access to the wireless infrastructure, using Cisco ISE, to allow configuration of the WLC syslog configuration?

A. MANAGEMENT

B. SECURITY

C. CONTROLLER

D. WIRELESS

Correct Answer: A

https://www.ibm.com/docs/en/dsm?topic=controllers-configuring-syslog-cisco-wireless-lan-controller https://www.cisco.com/c/en/us/support/docs/wireless-mobility/wireless-lan-wlan/91631-uwn-tacacs-config.html#:~:text=should%20be%20referred.-,Authorization,-Authorization%20is%20task

**QUESTION 3**

An engineer added more APs to newly renovated areas in building. The engineer is now receiving Out-of-Sync alarms on Cisco Prime Infrastructure. Which two actions resolve this issue? (Choose two.)

A. Manually synchronize from Cisco Prime Infrastructure.

B. Manually synchronize from MSE.

C. Enable automatic synchronization on Cisco Prime Infrastructure.

D. Enable automatic synchronization on MSE.

E. Add new APs to maps on Cisco Prime Infrastructure.

Correct Answer: BD

ref: https://www.cisco.com/c/en/us/td/docs/net_mgmt/prime/infrastructure/3-5/user/guide/bk_CiscoPrimeInfrastructure_3_5_0_UserGuide/bk_CiscoPrimeInfrastructure_3_5_0_UserGuide_chapter_0100110.html#con_1301578:~:text=NEs%20with%20MSE-,Set%20Up%20Synchronization%20Between%20MSE%20Databases%20and%20Product%20Database,-Manual%20synchronization%20of

**QUESTION 4**

A Cisco 8540 WLC manages Cisco Aironet 4800 Series APs and sends AoA data to a Cisco CMX 3375 Appliance for Hyperlocation. The load from the WLC is distributed to another virtual CMX server using CMX grouping. The virtual CMX server shows location RSSI data and not Hyperiocation. No AOA metrics are shown on the metrics page of the CMX virtual appliance under System > Metrics > Location Metrics.

How must the network administrator RESOLVE THIS ISSUE?

A. Allow port 2003 for AoA packets to flow through between the CMX appliances.

B. Enable Wireless > Access Points > Global configuration > Enable Hyperlocation on the WLC.

C. Use one Hyperlocation-enabled WL.C and CMX for AoA data

D. Enable the HALO module on the CMX appliance for the data collection

Correct Answer: C

**QUESTION 5**

A wireless network has been implemented to enable multicast video to be streamed reliably over the wireless link to the wireless users. After a client reports that the video is unable to stream, the administrator determines that the client is connecting at a data rate of 12 Mbps and is trying to stream to a valid multicast address on the network. Which two actions must be applied? (Choose two.)

A. Turn off IGMP snooping for all the configured WLANs on the controller.

B. Implement video-stream for the multicast video on the controller.

C. Allow multicast-direct to work correctly and multicast-direct to be enabled globally.

D. Change the WLAN QoS value to Bronze for the WLAN that multicast will be enabled.

E. Allow RTSP to stream the video due to wireless multicast not using acknowledgements.

Correct Answer: BC

[300-430 PDF Dumps](#)          [300-430 Study Guide](#)          [300-430 Exam Questions](#)