VCE & PDF
GeekCert.com

7004.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura® Maintenance Exam

Pass Avaya 7004.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.geekcert.com/7004-1.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Click the Exhibit button.

```
┌──────────────────────────────────────────┐
│ NPA 1912                                  │
├──────────────────────────────────────────┤
│ RLI 1                                     │
└──────────────────────────────────────────┘

┌──────────────────────────────────────────┐
│                 RLI 1                     │
├──────────────────────────────────────────┤
│ ENTR 0                                    │
├──────────────────────────────────────────┤
│ ROUT 3                                    │
├──────────────────────────────────────────┤
│ TOD 0 ON 1 ON 2 ON 3 ON                   │
│       4 ON 5 ON 6 ON 7 ON                 │
├──────────────────────────────────────────┤
│ CNV NO                                    │
├──────────────────────────────────────────┤
│ EXP NO                                    │
├──────────────────────────────────────────┤
│ FRL 5                                     │
├──────────────────────────────────────────┤
│ DMI 0                                     │
├──────────────────────────────────────────┤
│ FCI 0                                     │
├──────────────────────────────────────────┤
│ OHQ NO                                    │
├──────────────────────────────────────────┤
│ CBQ NO                                    │
├──────────────────────────────────────────┤
│                                           │
├──────────────────────────────────────────┤
│ ISET 1                                    │
├──────────────────────────────────────────┤
│ MFRL 0                                    │
└──────────────────────────────────────────┘
```

Consider the customer\'s current programming: NCOS of 2 = FRL of 2 Class of Service on all sets is CTD

With reference to the exhibit, how would you modify Route List Index 1 to permit all station users with an NCOS of 2 to place 1+912 calls?

A. Change FRL on Route List Index 1 to FRL 1

B. Change FRL on Route List Index 1 to FRL 4

C. Change FLI on NPA entry for 1214 to RLI 2

D. Leave all existing programming as is.

Correct Answer: A

QUESTION 2

Click the Exhibit button.

A customer has asked if the Communication Server 1000 RIs. 7 x system can provide Exchange users

with the ability to selectively drop people that have been added to a conference. Based on the print-outs,

what capabilities are currently available to the user of extension 2006?

A. The user cannot see the conferee display count or selectively disconnect callers.

B. Theuser can see the conferee display count and can selectively disconnect callers.

C. The user can see the conferee display count but cannot selectively disconnect callers.

D. The user cannot see the confereedisplay count butselectively disconnect callers.

Correct Answer: B

QUESTION 3

A customer is using Zone Based Dialing in their Networked Communication Server 1000 systems. Which prompt has been added to the telephone configuration overlays to allow IP telephones to be configured for this?

A. the DIA1__PLAN prompt (Type Of dialing plan for DN/CLIDdisplay)

B. the NZON prompt (Numbering Zone)

C. the NUMZONE prompt (Number of the Numbering Zone)

D. the NZDES prompt (NumberingZone Designator)

Correct Answer: C

QUESTION 4

Click the Exhibit button. You are responsible for maintaining a small Communication Server 1000 RIs. 7 x SA system. The customer decided against using Basic Automatic Route Selection (BARS) for call routing. They are now reporting that the user of extension 2001 is blocked when attempting to dial local call using the COT access code.

Based on the exhibit, what adjustments should be made to the system to allow the user of extension 2001 to dial local calls only by directly accessing the COT Route?

A. Change the Class of Service of extension 2001 to Semi Restricted (SRE) and leave the TGAR setting of two (2) on the COT Route.

B. Change the TGAR of extension2001 to zero and leave the Class of Service setting of Toll Denied (TLD) on extension 2001.

C. Change the Class of Service of extension 2001 to Conditionally Unrestricted (CUN),leave theTGAR setting of two (2) on the COT Route.

D. Change the TGAR of the COT Route to zero and change the Class of Service setting of extension 2001 to Conditionally Toll Denied (CTD)

Correct Answer: D

QUESTION 5

Click the Exhibit button.

TABLE A	TABLE B	TABLE C	TABLE D
SPN 61	SPN 61	SPN 61	SPN 61
RLI 2	RLI 3	RLI 4	RLI 5

RLI 2	RLI 3	RLI 4	RLI 5
ENTR 0	ENTR 0	ENTR 0	ENTR 0
ROUT 3	ROUT 3	ROUT 4	ROUT 3
TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON	TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON	TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON	TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON
CNV NO	CNV NO	CNV NO	CNV NO
EXP NO	EXP NO	EXP NO	EXP NO
FRL 5	FRL 2	FRL 5	FRL 5
ENTR 1	ENTR 1		ENTR 1
ROUTE 1	ROUTE 1		ROUTE 1
TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON	TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON		TOD 0 ON 1 ON 2 ON 3 ON 4 ON 5 ON 6 ON 7 ON
CNV NO	CNV NO		CNV NO
EXP NO	EXP NO		EXP NO
FRL 6	FRL 6		FRL 4

A customer\\'s dialing requirement, listed below, require that all station users assigned an NCOS of 3 and Class of Service of Conditionally Toll Denied (CTD) be able to place toll calls from the United States to Australia.

Australia Country Code: 61 NCOS of 3 has an FRL of 3 Expensive Routers are not being used

With reference to the exhibit, which table will allow all station users to be able to place these toll calls?

A. Provisioning Table A

B. Provisioning Table B

C. Provisioning Table C

D. Provisioning Table D

Correct Answer: B