HP0-S35$^{Q\&As}$

Implementing HP BladeSystem Solutions

Pass HP HP0-S35 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.geekcert.com/HP0-S35.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official
Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

A server is running out of disk space. It has a logical disk in external storage comprised of three, 72 GB disks in a Raid 5 configuration. No drive bays are available to add disks without adding another enclosure. You decide to replace the three 72 GB disks with three, 146 GB disks. you replace each disk on at a time allowing time for data to rebuild after each drive replacement. After creating a new logical drive in the unused space, you perform an array expansion and extension to combine the two logical disks, approximately how much space for data has been gained through these actions?

A. 148 GB

B. 210 GB

C. 292 GB

D. 438 GB

Correct Answer: A

QUESTION 2

An EBIPA is enabled for device and interconnect bays and all modules are set to use DHCP. Which statement is correct?

A. If a server is moved to another Slot, the iLO continues to use the IP address assigned from the previous slot.

B. The interconnect bay management ports use the same EBIPA address pool as the server bay

C. Each device on module will receive an IP address issued by the external DHCP server

D. Each Device or module will receive an IP address issued by EBIPA.

Correct Answer: B

QUESTION 3

What is called the concept of back up on a tape each night?

A. System Recovery

B. Business Continuity

C. Backup Strategy

D. Replication

Correct Answer: C

QUESTION 4

You are at a customer site and need to add new VLANs to an existing Virtual Connect domain. THe Virtual Connect Manager displays a message that it is locked, and there is a do not pass sign at the top of the web interface. What could cause this?

A. The VC domain reached the maximum number of VLANs

B. The VC firmware is on an old fimware revision

C. The VC domain is locked by Virtual Connect Enterprise Manager

D. You do not have proper right to make any VC domain changes

Correct Answer: C

QUESTION 5

Where can you find what exactly is included in a HP Installation Services CarePack?

A. CarePack Data Sheet

B. CarePack Lookup Tool

C. SPOCK

D. Insight Online

Correct Answer: A

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.geekcert.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: