DES-4421^{Q&As}

Specialist - Implementation Engineer, PowerEdge MX Modular Exam

Pass EMC DES-4421 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.geekcert.com/des-4421.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

An administrator has installed the iDRAC Service Module in the OS on a compute sled, they are unable to use its features in the iDRAC web GUI. What is the likely cause of this issue?

A. OS to iDRAC pass-through feature is not enabled in the iDRAC

B. iDRAC Express license is installed

C. OS and iDRAC are configured on different networks

D. Installed OS is not supported

Correct Answer: A

Reference: https://cdn.cnetcontent.com/syndication/mediaserver/inlinecontent/all/0ec/190/0ec19016bfa8284323b12b2a a8d7a07c/original.pdf

QUESTION 2

A new administrator has just taken over an MX7000 Multi-Chassis Management Group and two-racks of PowerEdge servers. The previous administrator no longer works at the company and is not available. No one knows the password for the OME-M interface and the default password is not working.

What must be used to reset the password?

A. iDRAC for one of the compute sleds.

B. Left ear control panel.

C. RACADM using a serial connection

D. Management Module jumpers

Correct Answer: D

Reference: https://www.dell.com/support/manuals/us/en/04/poweredge-mx7000/omem1.00.01_ug/recovering-passwords?guid=guid-553bf2dd-c491-4117-85f5-c2fbfde4ef12andlang=en-us

QUESTION 3

What is a benefit of SmartFabric Services Mode?

A. Topology validation and self-healing

B. Load balancing for management layers

C. Load balancing for application layers

D. Automatic detection of packet collisions

Correct Answer: B

QUESTION 4

A technician replaces a failed Management Module in an MX7000 chassis group. After the technician leaves the site, the administrator reports that the lead chassis is no longer able to communicate with its members. How can OME-M be used to confirm the cabling configuration?

A. View the health status of the lead Chassis Management Module

B. View the health status of the lead Chassis Management ports

C. View the I/O module topology map from the lead chassis

D. View the topology map from the Group Lead

Correct Answer: B

QUESTION 5

An MX7000 administrator has been tasked to perform the initial configuration of a new MX platform. The MX700 has seven MX740c, one MX5016s, two Management Modules (MMs), an LED-Only control panel, two MX9116n in Fabric A, two MX5108n in Fabric B, and two MX5000s in Fabric C.

What is a valid method to perform the initial MX platform configuration?

A. Use a serial DB9 / DB cable

B. Use KVM and racadm setniccfg command from MM configuration menu

C. Use Ethernet front panel port default DHCP address

D. Use QuickSync 2

Correct Answer: D

Reference:
https://infohub.delltechnologies.com/static/media/client/7phukh/d3df87a5-ddb7-4917-969d-24e249b52824.pdf

DES-4421 PDF Dumps   DES-4421 VCE Dumps   DES-4421 Exam Questions