VCE & PDF
GeekCert.com

H35-211^{Q&As}

HCIP-Access V2.5

Pass Huawei H35-211 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.geekcert.com/h35-211.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

(multiple) VoIP users can hear normal dial tone after picking up the phone, but after dialing, the dial tone does not stop. What are the possible reasons?

A. MGC did not issue signaling to stop dialing the dial tone.

B. The A/ law setting of the DSP subboard is inconsistent with the user board.

C. Adjacent user side slot small network is not removed

D. MG did not correctly report the off-hook signal

Correct Answer: ABD

QUESTION 2

(multiple) Which of the following are key technologies for VoIP?

A. Signaling technology

B. Real-time transmission technology

C. Network transmission technology

D. Media technology

Correct Answer: ABCD

QUESTION 3

(multiple) The called phone can ring normally but does not display the caller number. What are the possible reasons?

A. Softswitch does not have a caller ID configured

B. AG did not receive the caller ID information of the softswitch

C. The environment of the equipment room is not good, such as equipment, patch panels, grounding, etc.

D. The user\\'s phone does not support caller ID

Correct Answer: ABCD

QUESTION 4

(multiple) Querying the status of POWER4845 on the UA5000 has been a fault. What are the possible reasons?

A. The monitoring line sequence is incorrect or damaged.

B. The serial port where the monitor cable is plugged in is not correct.

C. The monitoring board hardware of the POWER4845 is damaged.

D. The communication protocol needs to be converted.

Correct Answer: ABCD

QUESTION 5

Single) When configuring multicast services on the MA5600T/MA5680T, the multicast VLAN program is statically configured. Which of the following options can be configured or not?

A. service-port

B. igmp user

C. igmp program

D. igmp profile

Correct Answer: D

H35-211 PDF Dumps   H35-211 Study Guide   H35-211 Exam Questions