

220-801^{Q&As}

CompTIA A+ Certification Exam

Pass CompTIA 220-801 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/220-801.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF GeekCert.com

https://www.geekcert.com/220-801.html

2024 Latest geekcert 220-801 PDF and VCE dumps Download

QUESTION 1

| Which of the following memory types is MOST commonly found in Pentium 4 class and newer des | ktop P | ₂ C | s? |
|---|--------|----------------|----|
|---|--------|----------------|----|

- A. SIMM
- **B. RAMBUS**
- C. SODIMM
- D. DIMM

Correct Answer: B

QUESTION 2

Which of the following is a standard Intel processor socket type?

- A. F
- B. 754
- C. 940
- D. LGA

Correct Answer: D

Reference. http://en.wikipedia.org/wiki/Land_grid_array

QUESTION 3

A technician encounters prohibited materials on a computer located in a common area that is used by several employees. Which of the following should be done FIRST?

- A. Remove the item from the computer
- B. Show to others so they can be a witness
- C. Copy the item to an external website
- D. Report the incident to management

Correct Answer: D

Reference. http://en.wikipedia.org/wiki/Computer_security_incident_management

QUESTION 4



https://www.geekcert.com/220-801.html

2024 Latest geekcert 220-801 PDF and VCE dumps Download

Which of the following connections are typically on the external PC chassis? (Select TWO).

- A. AGP
- B. SAS
- C. IEEE1394
- D. eSATA
- E. IDE

Correct Answer: CD

IEEE1394 commonly known as Firewire port and eSATA connections are typically located on the external PC chassis. Firewire port is a serial bus interface that works like a USB. eSATA connection are typically external hard disks.

QUESTION 5

A printer technician is sent to work on a fuser in a laser printer that is not adhering toner properly to the paper. While onsite Joe, an end user, reports that he has been having frequent paper jams as well. Which of the following would be the BEST course of action to repair the printer?

- A. Install a manufacturer recommended maintenance kit
- B. Install the fuser, replace the toner cartridge, and replace the pickup and separation rollers
- C. Install the fuser and also replace the high voltage power supply
- D. Install the fuser as the paper jams were probably also caused by the defective fuser

Correct Answer: A

220-801 PDF Dumps

220-801 VCE Dumps

220-801 Exam Questions