



# 3605<sup>Q&As</sup>

Avaya Ethernet Routing Switch Implementation and Maintenance Exam

## Pass Avaya 3605 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/3605.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





#### QUESTION 1

Routed Split Multilinking Trunking (RSMLT) is a way to ensure that traffic can be routed off the VLAN by adding router redundancy. RSMLT is configured on which Ethernet Routing Switch (ERS) configuration component?

- A. an OSPF router
- B. a core switch port
- C. a VLAN
- D. an SMLT

Correct Answer: A

---

#### QUESTION 2

Which SMLT resiliency feature uses the Soft Down option?

- A. extended Control Packet limit (ext-CP limit)
- B. discards untagged frames
- C. Simple Loop Prevention Protocol (SLPP)
- D. virtual Link Aggregation Control Protocol (VLACP)

Correct Answer: A

---

#### QUESTION 3

When configuring LINK aggregation, a technician created a Distributed Multi-Link Trunk (DMLT) group on the edge connecting switch cluster core. What gets distributed?

- A. Access ports
- B. VLANS
- C. Uplinks
- D. PVIDs

Correct Answer: C

---

#### QUESTION 4

A technician is configuring 802.1 Q tagging, VLACP with short timeout, untagged frames to be discarded. Which part of the network is being configured?



- A. layer 2 core
- B. layer 3 core
- C. the edge
- D. the uplinks

Correct Answer: D

---

#### QUESTION 5

A customer is upgrading an existing ERS 8610 with the 8692SF to software version 7.x. Which statement regarding the upgrade is correct?

- A. The customer must upgrade the 8692SF to an 8893SF for software release 7.x.
- B. The customer can run 7.x with the existing 8692SF, although some features will be disabled.
- C. The customer can add the SuperMezz module to the 8692SF and run release 7.x.
- D. The customer must upgrade to an ERS 8810 chassis to run software release 7.x.

Correct Answer: C

[Latest 3605 Dumps](#)

[3605 VCE Dumps](#)

[3605 Study Guide](#)