



7003.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura Implementation Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/7003-1.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

A technician has just installed and configured a System Manager as the primary security Server and configured a Member Security Server with the Element Manager and Subscriber Manager Applications deployed. The Communication Server (CS) 1000E RIs. 7x Call Server is part of this server security domain. All connections are up and running. When the new CS 1000 RIs. 7x system link on the elements window is clicked, the web browser returns with the following message.

"Destination IP address cannot be reached"

What is causing the problem?

- A. The browser window has not been refreshed.
- B. The Element Manager is unable to reach the MC32S via the ELAN.
- C. The Public Key Certificates for Web SSL were not added in the Call Server.
- D. The wrong Call Server IP address was entered during the application deployment.

Correct Answer: D

QUESTION 2

A customer has a Communication Server (CS) 1000RIs. 7x system and installing a stand-alone CPDC Signaling Server.


Which role should be chosen during the IP Telephony node Configuration?

- A. Backup
- B. Follower
- C. Leader
- D. Alternate

Correct Answer: C

QUESTION 3

Click the exhibit button.



A technician is provisioning a new Communication Server (CS) 1000 RIs. 7x system for a customer, and is adding an SIP virtual route using Element Manager Routes and Trunks.

What is the Trunk Type (TKTP)?

- A. Integrated Service Access route (ISA)
- B. TIE Trunk data block (TIE)
- C. Automatic (TIE AUTO)
- D. Direct inward Dialing trunk (DID)

Correct Answer: B

QUESTION 4

You customer just installed three Communication Servers 1000 RIs. 7x systems to support their new campus distributed corporate offices. The customer allowed for periodic synchronization of their corporate Lightweight Directory Access Protocol (LDAP) database with subscriber Manager.

Which Subscriber Manager Feature allows you to synchronize subscribers from an LDAP database and assign them to a telephone account of the same time?



- A. Bulk Account Creation
- B. CSV Subscriber Synchronization
- C. Account Synchronization
- D. Flow-through Provisioning

Correct Answer: D

QUESTION 5

A field calls about a problem enabling the DSPs on a new Communication Server (CS) 1000E SA Co-resident on release 7x. The DSPs on the MG 1 are all enabled but enabling the DSPs on MG2 and MG3 fail, and asked that the configuration be reviewed.

MG1: CPMG 128 MG2: MGC 128 DSP DB in position 2 MG3: MGC 128 DSP DB in position 2

After reviewing the configuration, an error in the DSP 128 VGW (DSP) configuration is identified? Which configuration option accurately reflects the proper configuration for the voice Gateway (DSP) channel?

- A. Numbering of VGW channels: 128Trunk data block VGWTerminal number: 004 0 02 0Designator field for trunk: DSPExtended trunk DSP DB 128Customer number: 00
- B. Numbering of VGW channels: 128Trunk data block VGWTerminal number:004 0 01 0Designator field for trunk: DSPExtended trunk DSP DB 128Customer number: 00
- C. Numbering of VGW channels: 128Trunk data block VGWTerminal number: 004 0 00 0Designator field for trunk: DSPExtended trunk DSP DB 128Customer number: 00
- D. Numbering of VGW channels: 128Trunk data block VGWTerminal number: 004 0 11 0Designator field for trunk: DSPExtended trunk DSP DB 128Customer number: 00

Correct Answer: D

[7003.1 PDF Dumps](#)

[7003.1 Study Guide](#)

[7003.1 Exam Questions](#)