



C4090-454^{Q&As}

IBM High-End Tape Technical Solutions V7

Pass IBM C4090-454 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/c4090-454.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by IBM Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

A customer is in the process of installing a two node TS7740 grid with a single production site. The second site used for DR is 50 km away. They want to set all logical volumes to have a size of 6 GB. What is a possible effect on the customer's tape workload?

- A. It may increase the recall time for logical volumes
- B. It may increase the amount of data stored on stacked volumes
- C. It may increase the mount time for fast ready scratch volumes
- D. It may increase the amount of data stored in the tape volume cache

Correct Answer: A

QUESTION 2

In a TS7700 R2.x system, how many logical paths are provided by the minimum FICON adapter configuration?

- A. 256
- B. 512
- C. 1024
- D. 2048

Correct Answer: B

QUESTION 3

What address space is used by z/OS to communicate with the TS7700?

- A. JES2 or JES3
- B. Workload Manager
- C. Object Access Method
- D. Catalog Address Space

Correct Answer: C

QUESTION 4



A banking customer's TS7740 was unable to replicate the tape backup data to the DR data center via the current grid network. The IBM support engineer had created a PMR with Severity 1 because the tape library is supporting the customer's production environment. Six hours after the PMR was created, IBM Level 2 support requested to change the Severity Level to 2, even though the problem had not been resolved. Based on IBM guidelines, why would this problem need to be reduced to Severity 2?

- A. Severity 1 only applies to Tape Failure
- B. Severity 1 only applies to Network Failure
- C. Severity 1 only applies to Production Failure
- D. Severity 1 problem must be resolved within 6 hours

Correct Answer: C

QUESTION 5

On a TS3500 Tape Library, what is the minimum number of cartridge cells that can be configured in an L23 frame?

- B. 58
- C. 117
- D. 248

Correct Answer: B

[C4090-454 VCE Dumps](#)

[C4090-454 Study Guide](#)

[C4090-454 Braindumps](#)