



HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/hp2-t23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

Which tool can you use to verify that SNMP events appear in HP SIM from a server blade running Windows 2008?

- A. Onboard Administrator
- B. System Management Homepage
- C. HP SNMP Agent
- D. Integrated Lights-Out

Correct Answer: B

QUESTION 2

Which components are integrated into the HP Service Pack for ProLiant (SPP)? (Select three)

- A. HP Advanced Diagnostic Utility
- B. HP Smart Update Firmware DVD
- C. HP Advanced Configuration Utility
- D. HP ProLiant Support Packs
- E. HP Smart Update Manager
- F. HP ProLiant Version Control DvD 24 of 60

Correct Answer: ADE

QUESTION 3

Which HP tool can you use to deploy firmware and software updates to a ProLiant server blade?

- A. Insight Diagnostics
- B. Software Update Manager
- C. System Management Homepage
- D. Service Pack for ProLiant

Correct Answer: B

QUESTION 4

You are viewing the current driver and firmware status in the Version Control Agent (VCA) and notice that only one



column of information is presented.

What must you do to see the current status and the latest revision available?

- A. Reboot the server to use the new VCA version, because the server has recently installed updates.
- B. Upgrade the System Management Homepage (SMH) VCA to the latest version to reflect the changes needed to access the new revisions.
- C. Set up the central management server (CMS) to check for the latest Service Pack for ProLiant (SPP) and push it to the VCA.
- D. Configure the VCA to use the Version Control Repository Manager (VCRM).

Correct Answer: B

QUESTION 5

A ProLiant DL 380 G7 server has a failure indicating that memory slot DIMM 1 has errors To troubleshoot the problem, you exchange the memory modules in slots 1 and 2 with each other.

Now you have a memory error indicating that memory slot 1 has errors, and an amber LED next to slot 1 is lit.

What should you do?

- A. Replace the memory module in slot 1 because it is definitely bad
- B. Replace both memory modules in slots 1 and 2
- C. Run the ECC memory test in the diagnostics to correct the errors
- D. Replace the system board and rerun the memory diagnostics.

Correct Answer: A

[HP2-T23 PDF Dumps](#)

[HP2-T23 VCE Dumps](#)

[HP2-T23 Study Guide](#)