



H13-341^{Q&As}

Huawei Certified internetwork Expert - Transmission

Pass Huawei H13-341 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/h13-341.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

Which of the following statements about avoiding the generation of discrete trails are correct?

- A. Use the trail function for configuration.
- B. For services configured on a per-NE basis, search for trails on the NMS to ensure that the service configurations are complete and standard.
- C. A fiber cut or switching test must be performed on the trail with protection routes to ensure that the configuration is complete and standard.
- D. Guide users to learn service configuration specifications.

Correct Answer: C

QUESTION 2

Which of the following statements about the line fiber quality monitoring performance parameters is wrong?

- A. The pulse width of emitted optical pulses varies according to monitoring modes, and affects the detection distance and measurement precision. A greater pulse width provides a larger dynamic range, longer detection distance and better measurement precision.
- B. When the pulse width increases, the light emitting time increases and consequently a larger energy is obtained. This means that a larger dynamic range can be acquired but also larger dead zones will result.
- C. Measurement is performed multiple times within the detection time. The average value is obtained based on the measurement result to improve the measurement precision. The actual duration from the time when a detection event starts to the time when the detection results are returned will be longer than the Detection time.
- D. The total fiber loss will affect the detection distance and dynamic range is fixed for the same detection mode. Therefore, a larger total fiber loss indicates a smaller detection distance.

Correct Answer: A

QUESTION 3

Which of the following statements about replacing the SCC board is incorrect?

- A. In the case of the 1+1 hot backup of the SCC board, replacing the control board does not affect services when the active/standby switchover is performed.
- B. After the SCC board is removed, the BD_STATUS and COMMUN_FAIL alarms are reported. After the new board goes online, these alarms need to be manually cleared.
- C. If the software version of the new SCC board is later than equipment version, clear the database of the SCC board, and then downgrade the software on the SCC board to the same version as the equipment.
- D. If the software version of the new SCC board is earlier than the equipment version, upgrade the software on the SCC board to the same version as the equipment.



Correct Answer: C

QUESTION 4

Which of the following functions is added to EX40 compared with X40?

- A. Monitors the optical power of a single channel.
- B. Supports optical-layer cross-connections.
- C. Fewer slots are occupied.
- D. More multiplexed and demultiplexed wavelengths

Correct Answer: A

QUESTION 5

Which of the following Optical NE types are defined in U2000?

- A. WDM_OEQ
- B. WDM_OTM
- C. WDM_OLA
- D. WDM_OADM

Correct Answer: A

[Latest H13-341 Dumps](#)

[H13-341 Study Guide](#)

[H13-341 Exam Questions](#)