

HP5-H08D^{Q&As}

Delta - Technical Essentials of HP Workstations

Pass HP HP5-H08D Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/hp5-h08d.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.geekcert.com/hp5-h08d.html

2024 Latest geekcert HP5-H08D PDF and VCE dumps Download

QUESTION 1

What is Thunderbolt technology?

- A. the technology behind the thinness of HP Z Mobile Workstation
- B. the industry brightest and most color-accurate display technology
- C. the industry fastest and most versatile I/O connection
- D. the industry fastest and most reliable hard drive technology

Correct Answer: C

QUESTION 2

Compared to the previous generations or HP desktop workstations (HP Z420.Z620. and Z820), what does thenew generation highlight?

- A. industrial design, slim-line optical, and support for DDR3 and DDR4 memory
- B. new processors, industrial design, support for DDR3. and DDR4 memory1
- C. new processors, slim-line optical, small 4U size, and DDR4 memory
- D. new processors, industrial design, slim-line optical, and DDR4 memory

Correct Answer: C

QUESTION 3

What is the predecessor to the HP Z440 workstation?

- A. HP Z220 workstation
- B. HP Z240 workstation
- C. HP Z400 workstation
- D. HP Z420 workstation

Correct Answer: D

QUESTION 4

Which products make up the current family of HP Mobile Z workstations?

A. HP ZBook 14. HP ZBook 17, and HP ZBook 18 mobile workstations



https://www.geekcert.com/hp5-h08d.html

2024 Latest geekcert HP5-H08D PDF and VCE dumps Download

- B. HP ZBook 12, HP ZBook15, and HP ZBook 17 mobile workstations
- C. HP ZBook 15, HP ZBook 17, and HP Z8ook 18 mobile workstations
- D. HP ZBook 14, HP ZBook 15, and HP ZBook 17 mobile workstations

Correct Answer: D

QUESTION 5

Which configuration is required when using 32-bit operating systems on HP 2440. 2640, and 2840workstations?

- A. Reduce CMOS clockspeed
- B. Switch BIOS to HP legacy mode
- C. Increase CMOS clock speed.
- D. Switch BIOS to UEFI mode.

Correct Answer: B

HP5-H08D PDF Dumps

HP5-H08D Practice Test

HP5-H08D Braindumps