



HPE0-S55^{Q&As}

Delta - Designing HPE Server Solutions

Pass HP HPE0-S55 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/hpe0-s55.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

You customer has completed a successful proof of Concept (PoC) consisting of a single frame with dual composers and virtual Connect SE 40GB F8 modules. The customer wants to: *add a second frame before they move into production *have unified management *have separate logical enclosure for each frame

What are basic steps to add the second frame?

- A. Move the standby composer to the second frame
- B. Disconnect the existing management ring, and then cable the FLM (frame link module) in the first frame to the FLMs in the second frame
- C. install a satellite module in the first frame
- D. Move the bottom VC module from the first frame to the second
- E. Move one of the uplinks from the FLM in the first frame to a FLM in the second

Correct Answer: E

QUESTION 2

An environmentally sensitive customer has a data center that operates with fresh air cooling. Which feature of HPE proLiant Gen10 servers makes them suitable to operate in the environment?

- A. HPE 1600w Flex Slot platinum Hot Plug Low Halogen power supply support
- B. Intel?Xeon-platinum 8180m Support
- C. ASHRAE AA compliance
- D. ACPI 6.1 compliance

Correct Answer: D

QUESTION 3

One of the DL380 Gen 10 servers in your infrastructure has failed to boot after a 3rd party PCIe NIC Was installed.

- A. HPE does not allow 3rd party PCIe cards.
- B. the latest support pack proLiant must be used before accessing any additional 3rd party product in the server.
- C. The manufacture did not digitally sing the correct firmware amd HPE secure Boot halted the process.
- D. The ILO interface did not have a current IP provided from DHCP.

Correct Answer: C



QUESTION 4

A customer has a ProLiant DL based Gen10 server solution hosting an I/O intensive 2TB database. The customer needs to dramatically increase the performance of their existing system.

- A. Install HPE Scalable persistence Memory
- B. Move the OS to an M2 SSO drive
- C. Update the current processor to a Xeon-platinum
- D. Install DO4 Smart Memory

Correct Answer: A

QUESTION 5

A customer has 10 HPE BladeSystem enclosures managed by HPE OneView. They want to add three HPE Synergy frames.

What is a proper procedure to manage a new HPE Synergy installation?

- A. Use HPE Composer for HPE Synergy frames management.
- B. Deploy HPE Global Dashboard for HPE synergy management.
- C. Add all frames to the existing HPE Oneview appliance.
- D. Deploy a dedicated HPE OneView appliance for HPE Synergy frames

Correct Answer: A

[HPE0-S55 VCE Dumps](#)

[HPE0-S55 Study Guide](#)

[HPE0-S55 Exam Questions](#)