

ISS-003^{Q&As}

Intel Server Specialist Certification Exam

Pass CompTIA ISS-003 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/iss-003.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF GeekCert.com

https://www.geekcert.com/iss-003.html

2024 Latest geekcert ISS-003 PDF and VCE dumps Download

QUESTION 1

Your customer finds that the server system R2000WT fans are running very fast. As an Intel Server Specialist you must advise which of the following conditions may cause this symptom? (Select ALL that apply).

- A. Wrong BIOS version
- B. Chassis intrusion has occurred.
- C. Processors are under very high workload.
- D. Wrong FRUSDR flashed.
- E. Processor socket pin bent
- F. Both processor sockets are populated
- G. One system fan is inoperable.
- H. Incompatible BMC revision and BIOS version
- I. BIOS settings have been set to default mode

Correct Answer: BCDG

QUESTION 2

Which of the following documents should be referred to for the CPU microcode version currently in use in the Intel server board?

- A. FRUSDR Release Notes
- B. BIOS Release Notes
- C. BMC Release Notes
- D. Technical product specification
- E. Supported processor list

Correct Answer: B

QUESTION 3

A customer has an Intel® Server System R2308WTTYS based on two Intel® Xeon® E5-2630L v3 processors. The customer tries to power on a virtual machine in Microsoft Hyper-V Manager but gets an error: "The virtual machine could not be started because the hypervisor is not running. Verify that the processor of the physical computer has a supported version of hardware-assisted virtualisation". Which of the following statements explains this case?

A. The BIOS version of the system is less than R01.01.0008.



https://www.geekcert.com/iss-003.html

2024 Latest geekcert ISS-003 PDF and VCE dumps Download

- B. Intel® Virtualization Technology is disabled in the BIOS.
- C. Hypervisor reinstallation is required.
- D. Intel® Xeon® E5-2630L v3 processor does not support virtualization technology.

Correct Answer: B

QUESTION 4

Which of the following sequences of RAID levels list the MOST redundant level to the LEAST redundant level in regard to their ability to withstand disk failure? A)RAID 1 B)RAID 5 C)RAID 10 D)RAID 6 E)RAID 0

A. D, B, C, A, E

B. C, D, B, A, E

C. D, C, B, A, E

D. B, D, A, C, E

Correct Answer: C

QUESTION 5

A customer calls you for support to know what needs to be changed to ensure that the server will not have difficulty in detecting attached drives. As an Intel Server Specialist, you advise that all of the following cabling configurations will detect drives successfully EXCEPT:

- A. SATA controller, connected to expander card, connected through non-expander backplane, connected to a SATA drive.
- B. SATA controller, connected through non-expander backplane, connected to a SATA drive.
- C. SAS controller, connected to expander card, connected through backplane, connected to a SATA drive.
- D. SAS controller, connected through an expander backplane, connected to an SSD drive.

Correct Answer: A

ISS-003 VCE Dumps

ISS-003 Practice Test

ISS-003 Braindumps