



500-920^{Q&As}

Cisco Data Center Unified Computing Infrastructure Troubleshooting
(DCITUC)

Pass Cisco 500-920 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/500-920.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

When server is booting from SAN, which command verifies the PLOGI sessions with the target?

- A. Lunmap
- B. Lunlist
- C. FCMap
- D. FClist

Correct Answer: B

QUESTION 2

You are in the process of upgrading your UCS M3 Server to a newer UCS M4 Server. You associate the Service Profile to the new UCS Server, but it fails to boot. You suspect of a failed boot hard drive. You check your RAID1 Boot LUN in UCS Manager, but see no error messages.

What could be causing the issue?

- A. The newer Cisco UCS M4 Server is using flash drives, not hard drives.
- B. The newer Cisco UCS M4 Server is using disks of larger capacity than the previous UCS M3 Server.
- C. A misconfiguration on the Service Profile Local Boot Policy.
- D. A misconfiguration on the Service Profile Local Disk Policy.

Correct Answer: A

QUESTION 3

Which statement is true regarding the UCS Manager GUI is showing "Overall Status Unassociated" in the General tab for a C-series server?

- A. The server has a service profile assigned, but has connectivity issues with UCS Manager.
- B. The server is not properly connected.
- C. The server does not have a service profile assigned, but has been discovered by UCS Manager.
- D. The server has been properly connected, but has not been discovered by UCS Manager.

Correct Answer: B



QUESTION 4

When configuring UCS SAN Connectivity to a 3rd Party FibreChannel Storage Array that is connecting directly to the UCS Fabric Interconnects, which option is Cisco recommended\?

- A. Connect the Storage Array to a RC Storage Port and Enable NPV Mode on the UCS Fabric Interconnects
- B. Connect the Storage Array to an Appliance Port and Enable NPV Mode on the UCS Fabric Interconnects
- C. Direct connectivity between UCS Fabric Interconnects and FibreChannel Storage Arrays is not supported
- D. Connect the Storage Array to a FC Storage Port and Enable Switching Mode on the UCS Fabric Interconnects
- E. Connect the Storage Array to an Appliance Port and Enable Switching Mode on the UCS Fabric Interconnects

Correct Answer: D

QUESTION 5

What is the likely cause of an intermittent SAN Boot fails?

- A. Misconfigured SAN boot target in the boot policy of the service profile
- B. LUN ID Mismatch
- C. FCoE used instead of FC
- D. Wrong boot order in the service profile

Correct Answer: A

[Latest 500-920 Dumps](#)

[500-920 Study Guide](#)

[500-920 Exam Questions](#)