

648-238^{Q&As}

Implementing Cisco Connected Physical Security 1 Exam

Pass Cisco 648-238 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/648-238.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF GeekCert.com

https://www.geekcert.com/648-238.html

2021 Latest geekcert 648-238 PDF and VCE dumps Download

QUESTION 1

A system administrator is adding a new LTS media server to Operations Manager.

Which three things must be configured? (Choose three.)

- A. IP address of the Operations Manager
- B. IP address of the LTS media server
- C. username and password for Operations Manager
- D. username and password for LTS media server
- E. password for Operations Manager
- F. password for LTS media server

Correct Answer: ABF

QUESTION 2

Which of the following reports are available in the Cisco Video Surveillance solution?

- A. User Configuration Report only
- B. Device Activity Report only
- C. Application History Report only
- D. User Configuration, Device Activity, and Application History reports are available in the Cisco Video Surveillance solution.
- E. User Configuration, Device Activity, and Application History reports are not available in the Cisco Video Surveillance solution

Correct Answer: E

QUESTION 3

In VSM 6.3.2, what is the maximum number of video panes that can be displayed at any given time in the VSOM Operators View?

- A. 4
- B. 8
- C. 16
- D. 32



https://www.geekcert.com/648-238.html

2021 Latest geekcert 648-238 PDF and VCE dumps Download

Correct Answer: C

QUESTION 4

On a properly qualified client PC that meets workstation requirements, streaming video appears choppy with ghosting artifacts. However, recorded clips that are extracted and saved to the local PC for playback do not display any quality issues.

What is causing the issue?

- A. H.264 video needs to "settle" in the recording for best quality.
- B. network path congestion, QoS, and/or bandwidth issues
- C. camera problem
- D. video card driver

Correct Answer: B

QUESTION 5

In VSM 6.3.2, how can PTZ cameras be controlled?

- A. USB joystick only
- B. USB mouse only
- C. PTZ interface control in VSOM only
- D. By a USB joystick, USB mouse, or PTZ control interface in VSOM.

Correct Answer: D

Latest 648-238 Dumps

648-238 Study Guide

648-238 Braindumps

https://www.geekcert.com/648-238.html

2021 Latest geekcert 648-238 PDF and VCE dumps Download

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.geekcert.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © geekcert, All Rights Reserved.