

9L0-012^{Q&As}

Mac Service Certification Exam

Pass Apple 9L0-012 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/9I0-012.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Apple
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF GeekCert.com

https://www.geekcert.com/9I0-012.html

2024 Latest geekcert 9L0-012 PDF and VCE dumps Download

QUESTION 1

Which of the following utilities helps to diagnose wireless network issues and is only available when running OS X v10.8.4 or later?

- A. Network Utility
- B. Network Diagnostics
- C. Wireless Diagnostics
- D. Network Setup Assistant

Correct Answer: C

Reference: https://support.apple.com/en-ap/HT202663

QUESTION 2

You are inspecting a MacBook Pro as part of your troubleshooting process. You note that two of the screws on the bottom case are damaged. There is no record of the computer being repaired on a previous occasion. If the resolution to the issue requires that you replace a part, how does your discovery of the stripped screws impact that repair?

- A. You need to thoroughly question the customer on previous repairs or attempted repairs by unauthorized service providers
- B. Make sure to inspect internal components and connections carefully to make sure that components were not damaged by someone tampering with the computer
- C. Complete the set of three modification tests as specified in GSX prior to opening the computer
- D. Classify the repair as ineligible for service and explain to the customer that you will not be able to complete any repairs

Correct Answer: C

Reference: http://tim.id.au/laptops/apple/imac/imac_27_mid10.pdf

QUESTION 3

You must know the AppleCare name of an Intel iMac before performing which of the following actions?

- A. Starting up from OS X Recovery HD.
- B. Running Mac Resource Inspector.
- C. Replacing the logic board
- D. Resetting the NVRAM.

Correct Answer: C



https://www.geekcert.com/9I0-012.html

2024 Latest geekcert 9L0-012 PDF and VCE dumps Download

Reference: https://discussions.apple.com/thread/1516765

QUESTION 4

Apple recommends a DIMM installation scheme for the Mac Pro (Late 2013) that:

- A. Increases processing power
- B. Enhances graphics processing
- C. Optimizes system cooling
- D. Enables use of special memory modules

Correct Answer: D

Explanation: Apple recommends that you use Apple-approved DIMMs. You shouldn\\'t use DIMMs from older Mac Pro computers in your new Mac Pro. You can purchase Apple-branded memory online from the Apple Store or by visiting an Apple Retail store or Apple Authorized Reseller . Reference: https://support.apple.com/en-us/HT6054

QUESTION 5

Which of the following 27-inch Apple Thunderbolt Display features is NOT available on the 27- inch Apple LED Cinema Display?

- A. Gigabit Ethernet port
- B. Mag Safe cable (85W)
- C. Kensington security slot
- D. Built-in 2.1 speaker system

Correct Answer: D

Reference: http://www.everymac.com/monitors/apple/studio_cinema/specs/apple-led-cinema- display-27inch-specs.html

9L0-012 PDF Dumps

9L0-012 VCE Dumps

9L0-012 Exam Questions