



E20-616^{Q&As}

Symmetrix Installation and Troubleshooting Specialist

Pass EMC E20-616 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/e20-616.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center


-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

Refer to the Exhibit.



What is the VMAX 10K component illustrated as 'B'?

- A. SIB
- B. Filler
- C. BE I/O
- D. FE I/O

Correct Answer: A

QUESTION 2

Refer to the Exhibit.



Server Rear



You are Enabling SMC on the Service Processor. Into which Ethernet port do you plug the IP cable?

- A. 8
- B. 7
- C. 6
- D. 5

Correct Answer: A

QUESTION 3

A banking customer reported performance a issue in their DB server, which is connected to a dedicated FA on a VMAX array. After initial analysis, a bottleneck was found on the FA level. The customer now plans to add two FAs to share the load. What needs to be considered when performing the upgrade?

- A. The new FA's director bit flags should be configured to match the existing one.
- B. The new FA bit flags automatically synchronize with other FAs where the host is attached.
- C. Disable all FA bit flags on the new FA so the host will continue using the existing FAs bit flags configuration.
- D. If you set Director bit flags globally using SymmWin INIT configuration, there is no need to set them on any individual director.

Correct Answer: C

QUESTION 4

A new customer has purchased a VMAX 40K array. During implementation they explain requirements for one application that requires a point-in-time copy of the primary volumes every 2 hours, and retention for three days. The change rate is expected to be low.

Which replication solution should be recommended?



- A. TimeFinder/Snap
- B. TimeFinder/Clone
- C. TimeFinder/VP Snaps
- D. TimeFinder/Mirror

Correct Answer: A

QUESTION 5

On a VMAX 10K, what is a Power Vault requirement?

- A. 20 vault devices per engine
- B. 32 vault devices per engine
- C. Vault devices are configured on the first five drives of all DAEs.
- D. Five vault drives per DA slice

Correct Answer: B

[E20-616 PDF Dumps](#)

[E20-616 Practice Test](#)

[E20-616 Study Guide](#)