



H13-611^{Q&As}

HCIA-Storage V5.0

Pass Huawei H13-611 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/h13-611.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

When determining hard disk performance, which of the following are relevant. (Multiple Choice)

- A. Rotational speed,
- B. Seek time,
- C. Transfer time.
- D. Transfer rate.

Correct Answer: ABD

QUESTION 2

Which of the following file system is most suitable for the storage of Big Data?

- A. NTFS
- B. EXT4
- C. HDFS
- D. BTRFS

Correct Answer: C

QUESTION 3

Statement

1: Fiber optic cables must be bended with a minimum radius of 10 centimeters. Statement

2:

Bends and dirt causes the light signal to be weaker and the sensor cannot detect the light pulse then.

A.

Statement 1 and 2 are true.

B.

Statement 1 is true; Statement 2 is false.

C.

Statement 1 is false; Statement 2 is true.

D.



Statement 1 and 2 are false.

Correct Answer: C

QUESTION 4

Statement 1: Multimode optic cables are usually longer than single mode cables. Statement 2: Sharp cable bends lead to weaker signal at the end of the cable.

- A. Statements 1 and 2 are both true.
- B. Statement 1 is true and statement 2 is false.
- C. Statement 1 is false and statement 2 is true.
- D. Both statements 1 and 2 are false.

Correct Answer: C

QUESTION 5

A user is having intermittent problems connecting to their shared network storage, A network technician is able to determine that there is a problem within the network cabling in between the workstation and the switch. All other users are able to connect successfully to the network. Which of the following is the MOST likely cause?

- A. Patch cable is a crossover cable instead of straight-through.
- B. Cable has been cut somewhere within the wall.
- C. Crosstalk and interference are occurring.
- D. Cable is not connected at the patch panel.

Correct Answer: C

[H13-611 VCE Dumps](#)

[H13-611 Study Guide](#)

[H13-611 Braindumps](#)