

## H31-341<sup>Q&As</sup>

HCIP-Transmission V2.5

### Pass Huawei H31-341 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/h31-341.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



# VCE & PDF GeekCert.com

### https://www.geekcert.com/h31-341.html

2024 Latest geekcert H31-341 PDF and VCE dumps Download

#### **QUESTION 1**

When the grooming service level of the line board is ODUflex, which of the following protection schemes can be supported?

- A. ODUk SPRing protection
- B. Tributary SNCP
- C. SW SNCP
- D. ODUk SNCP

Correct Answer: C

#### **QUESTION 2**

In the scenario where the non-convergence OTU processes OTN standard signals, both A and B are WDM sites. After receiving the OTUk\_TIM alarm on the client side, the OTU board at station A sends the OTUk\_BDI alarm to the upstream. When the TIM follow-up action is disabled, the alarm is no longer transmitted to the downstream. When the TIM follow-up action is enabled, an SF event is generated. The WDM side of the OTU board at station B reports the ODUk\_PM\_AIS alarm, and the ODUk\_PM\_AIS alarm is transmitted downstream. The client equipment reports this alarm. After the WDM side of the OTU board at station B receives the OTUk\_TIM alarm and the TIM follow-up action is disabled, the alarm is no longer transmitted to the downstream. When the TIM follow-up action is enabled, an SF event is generated. After the client side of station B processes the SF event, the client equipment reports the ODUk\_PM\_AIS alarm.

A. True

B. False

Correct Answer: A

#### **QUESTION 3**

For the MSTP equipment, the pass-through mode is used for VC-4 services by default, and the termination mode is used for VC12/VC3 services by default.

A. True

B. False

Correct Answer: A

#### **QUESTION 4**

Which of the following statements about MPLS is wrong?

A. MPLS has two planes: control plane and forwarding plane. The control plane is connection-oriented, the forwarding

# VCE & PDF GeekCert.com

#### https://www.geekcert.com/h31-341.html

2024 Latest geekcert H31-341 PDF and VCE dumps Download

plane is connectionless.

- B. MPLS is not a service or application. It is a standard routing and switching platform that supports various upper-layer protocols and services.
- C. In the packet transport field, the MPLS technology is mainly used to construct tunnels to carry various types of services (for example, TDM, ATM, and Ethernet) transmitted by PWE3 to implement end-toend transmission of services on packet networks.
- D. MPLS packet forwarding is based on labels.

Correct Answer: A

#### **QUESTION 5**

The troubleshooting methods that can be used to separate external faults are:

- A. Configuration Data Analysis
- B. Meter Test
- C. Replacement
- D. Loopback

Correct Answer: A

Latest H31-341 Dumps

H31-341 VCE Dumps

H31-341 Practice Test