



# LSSWB<sup>Q&As</sup>

Lean Six Sigma White Belt

**Pass GAQM LSSWB Exam with 100% Guarantee**

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.geekcert.com/lsswb.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by GAQM  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





#### QUESTION 1

What is an OC Curve in sampling process?

- A. A diagram representing the probability of acceptance for a lot.
- B. A curve which indicates the percentage of bad quality products in a lot.
- C. A diagram which indicates the rate of production per day.
- D. None of these.

Correct Answer: A

---

#### QUESTION 2

What is Inferential Statistics in six sigma?

- A. This is the method of determining process capabilities.
- B. This method shows the statistics of the process.
- C. This method shows the process of production.
- D. None of the above.

Correct Answer: A

---

#### QUESTION 3

The relationship matrix in QFD shows whether the final technical requirements adequately address the customer requirements.

- A. True
- B. False

Correct Answer: A

---

#### QUESTION 4

A trend (in control charting) is typically described as:

- A. Seven points in a row either above or below the center line
- B. Seven points in a row in either an upward or downward direction
- C. Seven points in a row that are beyond the control limits



D. Seven data points in a subgroup

Correct Answer: B

---

#### QUESTION 5

The grand average of the subgroup averages is known as:

A. X-bar bar

B. X-double bar

C. The grand average

D. All of the above

Correct Answer: D

[LSSWB Practice Test](#)

[LSSWB Exam Questions](#)

[LSSWB Braindumps](#)